# Mipa Steinschlagschutz

Technical data sheet

Page 1 / 2



#### Intended use

Mipa Steinschlagschutz UBS is a durable corrosion protection for floor pans, entry sections and wheel houses. Excellent sound deadening properties, therefore this product is also suitable for car boots, bonnets and so on. Excellent adhesion, shock and scratch resistance, free from asbestos, fast drying, permanently elastic also in extreme temperature fluctuations, recoatable and after drying resistant to cold cleaner.

Spreading rate: 2,0 m²/l (for 500 µm DFT)

### Processing instructions \_



#### Colour

black, light grey, white



## Mixing ratio Hardener

by weight (lacquer : hardener) by volume (lacquer : hardener)

<del>--</del>



### Hardener

for complete paintwork for partial paintwork



### Pot life

--



### Thinner

ready for use



# Spray viscosity

gravity spray gun Airmix/Airless



### **Application mode**

Application modeHardenerpressure (bar)nozzle (mm) spray passesThinnerunderbody spray gun/ - UBS4 - 65 - 102--



### Flash-off time

5 - 8 min between coats

### Dry coat thickness

500 μm



### **Drying time**

| object<br>temperature | dust dry | set to<br>touch | ready for<br>assembly | sandable | recoatable |
|-----------------------|----------|-----------------|-----------------------|----------|------------|
| 20 °C                 |          |                 |                       |          | 1 - 2 h    |

Version: en 1120

# Mipa Steinschlagschutz

### Technical data sheet

Page 2 / 2



Note

**Storage:** at least 2 years in unopened original container

**VOC Regulation :** EU limit value for this product (category B/e): 840 g/l

This product contains max. 840 g/l of VOC.

**Processing conditions:** from +10 °C and up to 80 % relative humidity. Ensure adequate air ventilation.

**Processing instructions:** The floor pan must be cleaned thoroughly and must be dry, free from dust, grease, oil

and rust. Old non-adherent underbody coating must be removed. Mask beforehand motor, exhaust pipes, stub axles, cardan shaft and brake system as they must not be

sprayed!